Annual inspection report

1. Summary

Forty-eight sites were inspected between March and September 2026. Most sites passed; sites marked Follow-up need a second visit before 31 December 2026.

Overall status: **11 sites need follow-up** (see table below).

Methodology: pdfplumber.dev/cookbook/

2. Results by site

Site	Result	Reading (ppb)
Site 01	Pass	3.9
Site 02	Pass	11.9
Site 03	Pass	7.2
Site 04	Pass	7.3
Site 05	Pass	14.4
Site 06	Pass	3.1
Site 07	Pass	2.9
Site 08	Pass	10.8
Site 09	Follow-up	9.8
Site 10	Pass	8.3
Site 11	Follow-up	8.7
Site 12	Follow-up	5.2
Site 13	Pass	3.5
Site 14	Pass	9.7

Table continues on the next page.

Site	Result	Reading (ppb)
Site 15	Pass	4.4
Site 16	Pass	8.4
Site 17	Follow-up	4.0
Site 18	Pass	13.7
Site 19	Pass	1.1
Site 20	Pass	4.9
Site 21	Pass	6.9
Site 22	Pass	1.5
Site 23	Pass	10.4
Site 24	Follow-up	1.6
Site 25	Follow-up	7.0
Site 26	Pass	12.2
Site 27	Follow-up	7.8
Site 28	Pass	11.0
Site 29	Pass	2.6
Site 30	Pass	3.4
Site 31	Pass	13.6
Site 32	Pass	5.8
Site 33	Pass	6.3
Site 34	Pass	2.6
Site 35	Pass	13.1
Site 36	Pass	2.4
Site 37	Pass	12.4
Site 38	Follow-up	4.0
Site 39	Pass	4.0
Site 40	Follow-up	7.9
Site 41	Follow-up	1.3
Site 42	Pass	8.7
Site 43	Pass	8.9
Site 44	Follow-up	6.4
Site 45	Pass	10.1
Site 46	Pass	3.3
Site 47	Pass	7.9
Site 48	Pass	7.0